

## SPECTROM™ TURBO-FLO™ SPARE PART AVAILABILITY TRANSITION TO WILDEN

Please note, correction on the air valve pistons as mentioned in SB1009 will not be available for purchase through Wilden Pump and Engineering nor through Spectrom™.

If air valve pistons need replacing, Wilden recommends replacing the air valve assembly (i.e. 02-2000-07, 04-2000-07, etc.) to maximize performance and reliability. Distributors who are interested in purchasing these select Turbo-Flo™ spare parts can contact their Wilden Regional Sales Manager or Wilden, Grand Terrace, CA.

PARTS NO LONGER AVAILABLE FOR SALE		
Part Description	Spectrom™ Item No.	Wilden Item No.
Air Valve Piston, T1	S01-2250-11	01-2250-11
Air Valve Piston, T2	S02-2250-11	02-2250-11
Air Valve Piston, T4	S04-2250-11	04-2250-11
Air Valve Piston, T8	S08-2250-11	08-2250-11
Air Valve Piston, T15	S15-2250-11	15-2250-11

